



Photo #1 – Inlet side with laid up stone headwall



Photo #2 – Looking Downstream From Inlet of Structure – Pipe failure at top of pipe





Photo #3 – Outlet End of Pipe – Rotted pipe folding in on itself



Photo #4 – Outlet End of Pipe – Separation of last length of pipe and second to last length of pipe






Photo #5 – Outlet End – Erosion of surrounding area near pipe separation in Photo #4





Photo #6 – Looking downstream from road of erosion at pipe separation in Photo #4



Photo #7 – Looking south down Cayuga Heights Rd.





Photo #8 – Looking north down Cayuga Heights Rd.





Photo #9 – Looking north at the outlet end of separation in Photo #4.